ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
10

Ward Name
Dodda Bommasandra

Street ID
W0054, W0091, W0058, W0107, W0043, W0027, W0015, W

Street Name
NA, Om Shakthi Lyt 3rd Crs, Subhash Chandra Bose Lyt, Om Shakthi Lyt 8th Crs

Significant Landmark
chamundswari and nanjappa layout

Segment No.
10/S-W0054/S091316

Total Length (m)
843.55

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	132.10	77.555102	13.067125	77.556283	13.066832	W0085	W0105
2	131.29	77.555214	13.067440	77.556402	13.067211	W0085	W0105
3	580.16	77.554941	13.069050	77.560129	13.067773	W0065	RI-A23

Work Details

History of Road / Lane / Circles

Name of the Work
Construction of missing covering slab in chamundswari layout and nanjappa layout in ward no 10 Doddabommasandra Vidyaranayapura Sub-Division Yelaha

Sanctioned Estimated Amount (Rs.)
2000000

Sanctioned Year
2015

Year
2015 - 2016

Type of Work
Road

Other Work Type

Tender
Tender

Work Details
Construction of missing covering slab in chamundswari layout and nanjappa layout in ward no 10 Doddabommasandra Vidyaranayapura Sub-Division Yelahanka zone

Job No. / Work Code
010-16-000017

Work Order No.
EE/BTP/BBMP/E-PMT/227/2015-16

Work Order Date
26/02/2016

Period of Extention
90 DAYS

Defect Liability Period From
26/02/2016

Defect Liability Period To
25/02/2017

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)

K.V SUBBAREDDY	0.00

Phone No. **E-Mail ID**

9980915550

Field Inspection Details

Number of Trees	Any Other Information	Name
24		MADHAVA RAO
Date of Inspection	**Remarks**	
24/08/2016	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 10 **Ward Name:** Dodda Bommasandra **Street ID:** W0054, W0091, W0058, W0107,

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	24/08/2016	23/09/2016	COMPLETED
SE	VASU K M	24/08/2016	23/09/2016	COMPLETED
EE	YARAPPA REDDY	24/08/2016	23/09/2016	COMPLETED
AEE	SHIVAKUMAR	24/08/2016	23/09/2016	COMPLETED
AE	MADHAVA RAO	24/08/2016	23/09/2016	COMPLETED
AE	MADHAVA RAO	24/08/2016	23/09/2016	COMPLETED